Photo Album for Comstock Dept. of Fire and Rescue MI Job # 43560 W/O # 33789181 July 12, 2025

Since the last report the cab and pump house finished with paint and the body was still in staging (no photos). Next week the cab may begin to receive trim and wiring harnesses and the pump house may begin final pump assembly. The body may begin to receive trim and wiring harnesses.



DSC00404





DSC00406



DSC00427





DSC00428



DSC00430



DSC00429





http://reliantfire.com/



An Oshkosh Corporation Company

