


# In-Production Photo Report for Clinton Township Fire Department, MI Job# 39726-02

---

Status as of August 01, 2025

In this report your cab completed initial assembly and was merged with the frame, the pump house was staged, and the body completed paint and began initial assembly. In the next report the pump house may be installed on the chassis while the body may continue initial assembly.





DSC00176



DSC00177




DSC00178



DSC00179



DSC00180



DSC00181



DSC00182



DSC00183



DSC00184



DSC00185



DSC00186



DSC00187



DSC00188



DSC00189



DSC00190



DSC00260



DSC00261



DSC00262



DSC00263



DSC00264



DSC00265



DSC03272



DSC03273



DSC03274



DSC03275



DSC03276



<https://reliantfire.com/>



An Oshkosh Corporation Company