

# Photo Album for Comstock Dept. of Fire and Rescue MI Job # 43560 W/O # 33789181 August 16, 2025

Since the last report the cab was mounted and the pump house was in staging. The body was unavailable for photos. Next week the pump house could be mounted, and the body should begin to receive trim and wiring harnesses.



DSC00195



DSC00196



DSC00197



DSC00198






DSC00199



DSC00200



DSC00201



DSC00202



DSC00203



DSC00204



DSC00205



DSC00206






DSC00207



DSC00208



DSC00209



DSC00381





DSC00382



DSC00383



DSC00384



<http://reliantfire.com/>



An Oshkosh Corporation Company