


In-Production Photo Report for Gaines Charter Township, MI Job# 39765


Status as of August 08, 2025

In this report your cab was being prepped to release to paint. In the next report your cab may be staged to begin the paint process.






DSC03015



DSC03016



DSC03017



DSC03018



<https://reliantfire.com/>



An Oshkosh Corporation Company