


# In-Production Photo Report for Sault Ste. Marie Fire Department, MI Job# 43629

---

Status as of August 15, 2025

In this report your cab completed fabrication, the pump house structure began fabrication, and the body began fabrication. In the next report your cab may be staged, the pump house structure may complete fabrication, and the body may continue the fabrication process.






DSC03278



DSC03279



DSC03280




DSC03192





DSC03193



DSC03223



DSC03224



DSC03225



DSC03226



DSC03227



<https://reliantfire.com/>



An Oshkosh Corporation Company