



# In-Production Photo Report for Town of Burlington Fire Department, WI Job# 39979

Status as of December 05, 2025

In this report your cab completed fabrication and began the paint process while the pump house structure was fabricated. In the next report your cab may continue through paint while the pump house may begin initial assembly.







DSC00602



DSC00603



DSC00604



DSC00605



DSC00606



DSC03079



DSC03080



DSC03081



DSC03082



DSC03083



<https://reliantfire.com/>



An Oshkosh Corporation Company