

In-Production Photo Report for


Walker Fire Department, IA

Job# 40755 : PWO# 32027542

Status as of December 19, 2025

In this report your commercial chassis was staged to begin preparations for fire and emergency use (no photos), the pump house continued initial assembly, and the body completed the paint process. In the next report your chassis may remain staged, the pump house may be painted then continue initial assembly, and the body may be staged to begin initial assembly.





DSC07220



DSC07221



DSC07222



DSC07223



DSC07224



DSC07139



DSC07140



DSC07141



DSC07142



DSC07143



<https://reliantfire.com/>



An Oshkosh Corporation Company