

# In-Production Photo Report for Waterford Regional Fire Department, MI Job# 44365 : PWO# 34367054

---

Status as of February 13, 2026

In this report your cab was staged (no photos), the frame was unavailable for photos, the pump house began initial assembly, and the body completed fabrication and began the paint process with metal finishing. In the next report your cab may remain staged, the frame may be staged, the pump house may continue initial assembly, and the body may continue through paint.





DSC07081



DSC07082




DSC07083



DSC07084



DSC07085



DSC07283



DSC07284



DSC07285



DSC07286



DSC07287



<https://reliantfire.com/>



An Oshkosh Corporation Company