


# In-Production Photo Report for Waterford Regional Fire Department, MI Job# 44365 : PWO# 34367054

---

Status as of February 20, 2026

In this report your cab began the paint process, the frame arrived and was staged, the pump house continued initial assembly, and the body completed paint. In the next report your cab may continue through paint, the frame may be staged, the pump house may be painted then continue initial assembly, and the body may remain staged to begin initial assembly.





DSC07371



DSC07372



DSC07373



DSC07374



DSC07375



DSC07425



DSC07426



DSC07427



DSC07428



DSC07429



DSC07430



DSC07000



DSC07001




DSC07002



DSC07003



DSC07004



DSC07405



DSC07406



DSC07407



DSC07408



DSC07409



<https://reliantfire.com/>



An Oshkosh Corporation Company