



In-Production Photo Report for West Bend Fire Department, WI Job# 39895

Status as of February 27, 2026

In this report your cab continued the paint process. In the next report your cab may continue through paint.





Job # 39895
Bottom: #145 Red
Bottom: #145 Red
Bottom: #145 Red

Trim on Paint Break:
Leaf on Paint Break
Chrome Molding
Wheel/Ent/Dash CF:


DSC02863



DSC02864



DSC02865



DSC02866



DSC02867



<https://reliantfire.com/>



An Oshkosh Corporation Company