

In-Production Photo Report for

Lisbon, WI

Job# 44427 : PWO# 34384374

Status as of March 06, 2026

Congratulations - Your new Pierce apparatus is now in production at the Bradenton, FL facility! This week your commercial chassis arrived, the pump plumbing began assembly, and the body began fabrication. In the next report your chassis may be staged, the pump may continue assembly, and the body may complete the fabrication process.



Oshkosh Corporation Classification - Restricted

QUALITY SYSTEM FORM	QSF10-0836
Title: Window Sheet	Effective Date: 05/12/23
	Page 1 of 2

4374 Job #: 44427-1
L40X1TJ231246
on Fire Department - WI
er: Russo, Mark
Apparatus, Inc Yes No

DSC07420



DSC07421



DSC07422



DSC07423



DSC07424



DSC07425



DSC07426



DSC07427




DSC07428



DSC07429



DSC07430



DSC07601



DSC07602




DSC07603




DSC07604



DSC07605



DSC07606



DSC07431



DSC07432



DSC07433



DSC07434



DSC07435



DSC07436



<https://reliantfire.com/>



An Oshkosh Corporation Company