

# In-Production Photo Report for

Lisbon, WI


Job# 44427 : PWO# 34384374

---

Status as of March 27, 2026

In this report your commercial chassis remained staged (no photos), the pump house was painted then staged to continue initial assembly, and the body completed the paint process. In the next report your chassis may remain staged, the pump house may continue initial assembly, and the body may remain staged to begin initial assembly.





DSC07124



DSC07125




DSC07126



DSC07127



DSC07128



DSC07336



DSC07337



DSC07338



DSC07339



DSC07340



<https://reliantfire.com/>



An Oshkosh Corporation Company