


In-Production Photo Report for Waterford Regional Fire Department, MI Job# 44365 : PWO# 34367054

Status as of March 06, 2026

In this report all components were staged while the frame was unavailable for photos. In the next report the cab may begin initial assembly, the frame may remain staged, the pump house may be painted then continue initial assembly, and body may remain staged to begin initial assembly.





DSC07414



DSC07415



DSC07416




DSC07417



DSC07418



DSC07419



DSC07016



DSC07017




DSC07018



DSC07019



DSC07020



DSC07180



DSC07181



DSC07182



DSC07183



DSC07184



DSC07185



<https://reliantfire.com/>



An Oshkosh Corporation Company