

In-Production Photo Report for West Bend Fire Department, WI Job# 39895

Status as of March 13, 2026

In this report your cab completed paint, the pump house structure was fabricated, and the body was unavailable for photos. In the next report your cab may complete remain staged to begin initial assembly, the pump house structure may be staged, and the body may be available to photograph.





DSC02058



DSC02059



DSC02060



DSC02061



DSC04080



DSC04081



<https://reliantfire.com/>



An Oshkosh Corporation Company