


In-Production Photo Report for West Bend Fire Department, WI Job# 39895

Status as of March 20, 2026

In this report your cab began initial assembly, the pump house began initial assembly, and the body began the paint process. In the next report your cab may continue initial assembly, the pump house may continue initial assembly, and the body may continue through paint.





DSC02119




DSC02120



DSC02121




DSC04083




DSC04084



DSC04085



DSC04086



DSC02612



DSC02613



DSC02614



DSC02615



DSC02616



<https://reliantfire.com/>



An Oshkosh Corporation Company