

# In-Production Photo Report for Grand Traverse Metro Fire Department, MI Job# 44664

---

Status as of April 10, 2026

In this report your cab began initial assembly, the frame build continued, the pump house was painted then staged to continue initial assembly, and the body completed fabrication. In the next report your cab may continue initial assembly, the frame build may continue, the pump house may continue initial assembly, and the body may begin the paint process.






DSC02052



DSC02053



DSC02054



DSC02134



DSC02135




DSC02136



DSC02137



DSC02138



DSC04011



DSC04012



DSC04013




DSC04053



DSC04054



DSC04055



DSC04561



DSC04562



DSC04563



DSC04564



DSC04565



<https://reliantfire.com/>



An Oshkosh Corporation Company