


In-Production Photo Report for City of Iowa City Fire Department, IA Job# 40201-02

Status as of April 10, 2026

In this report your cab and pump house were merged with the frame while the body was in queue to be installed. In the next report the body should be installed on the chassis, and your apparatus may begin final assembly.






DSC02430



DSC02431




DSC02432




DSC02433



DSC02434



DSC02435



DSC02436



DSC02437



DSC02438



DSC02439



DSC02440



<https://reliantfire.com/>



An Oshkosh Corporation Company