

In-Production Photo Report for


Lisbon, WI

Job# 44427 : PWO# 34384374

Status as of April 03, 2026

In this report your commercial chassis remained staged (no photos), the pump house continued initial assembly, and the body began initial assembly. In the next report your chassis may begin preparations for fire and emergency use while the pump house and the body may complete initial assembly.





DSC07663




DSC07664



DSC07665



DSC07666



DSC07667



DSC07668




DSC07669



DSC07670



DSC07671




DSC07016



DSC07017



DSC07018



DSC07019



DSC07020



DSC07021



<https://reliantfire.com/>



An Oshkosh Corporation Company