In-Production Photo Report for

Plainfield Township Fire Department, MI

Job# 45693

Status as of September 25, 2026

In this report your cab completed paint and began initial assembly, the frame build began, the pump house continued initial assembly, and the body completed fabrication. In the next report your cab may continue initial assembly, the frame build may continue, the pump house may continue initial assembly, and the body may remain staged to begin the paint process.

Pierce
An Oshkosh Corporation Company

Find us on Facebook

RELIANT · FIRE · APPARATUS
F R A



DSC02159



DSC02160



DSC02161



DSC02162



DSC02163



DSC01181



DSC01182



DSC04125



DSC04126



DSC04127



DSC04689



DSC04690



DSC04691



DSC04692



DSC04693

https://reliantfire.com/

Find us on Facebook

An Oshkosh Corporation Company