
In-Production Photo Report for

Glen Lake Fire Department, MI

Job# 45348

Status as of October 16, 2026



In this report the chassis was staged to continue assembly while the body completed initial assembly and was in queue to be installed. In the next report the body may complete installation on the chassis and your apparatus may begin final assembly.

Pierce
An Oshkosh Corporation Company

Find us on Facebook


RELIANT FIRE APPARATUS



DSC01623



DSC01624




DSC01625




DSC01626



DSC01627



DSC01628



DSC01629



DSC01630



DSC01631



DSC01617



DSC01618



DSC01619



DSC01620



DSC01621



DSC01622

https://reliantfire.com/

Find us on Facebook

An Oshkosh Corporation Company