In-Production Photo Report for

Hazelhurst Fire Department, WI

Job# 45439 : PWO# 35137721

Status as of October 30, 2026

In this report chassis prep continued while the body continued the paint process. In the next report your chassis may continue preparations for fire and emergency use while the body may complete the paint process.

Pierce
An Oshkosh Corporation Company

Find us on Facebook

RELIANT FIRE APPARATUS



DSC06320



DSC06321



DSC06322



DSC06323



DSC06324



DSC06274



DSC06275



DSC06276



DSC06277



DSC06278

https://reliantfire.com/

Find us on Facebook

An Oshkosh Corporation Company