In-Production Photo Report for

Town of Minocqua Fire Department, WI

Job# 45349 : PWO# 35074263

Status as of October 02, 2026

In this report your commercial chassis was staged, the pump house completed test, and the tank and the body remained staged. In the next report the pump house may be installed on the chassis, the tank may remain staged, and the body may begin initial assembly.

Pierce
An Oshkosh Corporation Company

Find us on Facebook

RELIANT FIRE APPARATUS



DSC06066



DSC06067



DSC06068



DSC06069



DSC06070



DSC06268



DSC06269



DSC06270



DSC06271



DSC06272



DSC06253



DSC06254



DSC06255



DSC06256



DSC06257



DSC06178



DSC06179



DSC06180



DSC06181



DSC06182

https://reliantfire.com/

Find us on Facebook

An Oshkosh Corporation Company