In-Production Photo Report for

Plainfield Township Fire Department, MI

Job# 45693

Status as of October 02, 2026

In this report your cab continued initial assembly, the frame build continued, the pump house was painted then staged to continue initial assembly, and the body began the paint process. In the next report your cab may continue initial assembly, the frame build may continue, the pump house may continue initial assembly, and the body may continue through paint.

Pierce
An Oshkosh Corporation Company

Find us on Facebook


RELIANT · FIRE · APPARATUS
F R A



DSC01147



DSC01148




DSC01149



DSC01150



DSC01151



DSC01192




DSC01193



DSC01194



DSC01195



DSC01196



DSC01197



DSC01198



DSC01199



DSC01200




DSC01201



DSC05093



DSC05094




DSC05095



DSC05096



DSC05097



DSC02460



DSC02461



DSC02462



DSC02463

https://reliantfire.com/

Find us on Facebook

An Oshkosh Corporation Company