In-Production Photo Report for

Plainfield Township Fire Department, MI

Job# 45693

Status as of October 08, 2026

In this report your cab completed initial assembly, the frame build continued, the pump house completed initial assembly, and the body continued through paint. In the next report your cab and pump house may be staged, the frame build may continue, and the body may continue the paint process.

Pierce
An Oshkosh Corporation Company

Find us on Facebook

RELIANT · FIRE · APPARATUS



DSC01152



DSC01153



DSC01154



DSC01155



DSC01156



DSC01157



DSC01158



DSC01322



DSC01323



DSC01324



DSC01325



DSC01326



DSC04071



DSC04072



DSC04073



DSC04398



DSC04399



DSC04400



DSC04401



DSC04402

https://reliantfire.com/

Find us on Facebook

An Oshkosh Corporation Company