In-Production Photo Report for

Riverside Fire Department, IA

Job# 45267 : PWO# 35012265

Status as of October 16, 2026

In this report the chassis continued assembly, the pump house completed initial assembly, and the body continued initial assembly. In the next report your chassis may continue assembly, while the pump house may begin testing, and the body may complete initial assembly.

Pierce
An Oshkosh Corporation Company

Find us on Facebook

RELIANT FIRE APPARATUS



DSC06839



DSC06840



DSC06841



DSC06842



DSC06843



DSC06665



DSC06666



DSC06667



DSC06668



DSC06669



DSC06755



DSC06756



DSC06757



DSC06758



DSC06759

https://reliantfire.com/

Find us on Facebook

An Oshkosh Corporation Company