In-Production Photo Report for

Hazelhurst Fire Department, WI

Job# 45439 : PWO# 35137721

Status as of November 13, 2026

In this report your commercial chassis completed preparations for fire and emergency use, the pump house was staged to continue initial assembly, and the body completed the paint process. In the next report the chassis and the body may remain staged while the pump house may continue initial assembly.

Pierce
An Oshkosh Corporation Company

Find us on Facebook

RELIANT · FIRE · APPARATUS · FRA



DSC06015



DSC06016



DSC06017



DSC06018



DSC06019



DSC06180



DSC06181



DSC06182



DSC06183



DSC06184



DSC06065



DSC06066



DSC06067



DSC06068



DSC06069

https://reliantfire.com/

Find us on Facebook

An Oshkosh Corporation Company