In-Production Photo Report for

Sauble – Elk Eden Fire Department, MI

Job# 42818 : PWO# 33290205

Status as of November 06, 2026

In this report your chassis remained staged, the pump house completed initial assembly and was staged for testing, and the body completed initial assembly. In the next report the pump house and the body may be merged with the chassis at the start of initial apparatus assembly.

Pierce
An Oshkosh Corporation Company

Find us on Facebook

RELIANT FIRE APPARATUS



DSC06010



DSC06011



DSC06012



DSC06013



DSC06014



DSC06307



DSC06308



DSC06309



DSC06310



DSC06311



DSC06247



DSC06248



DSC06249



DSC06250



DSC06251

https://reliantfire.com/

Find us on Facebook

An Oshkosh Corporation Company