In-Production Photo Report for

Sauble – Elk Eden Fire Department, MI

Job# 42818 : PWO# 33290205

Status as of November 13, 2026



In this report the pump house and the body were merged with the chassis at the start of initial apparatus assembly. In the next report your apparatus may complete initial assembly and begin final assembly.

Pierce
An Oshkosh Corporation Company

Find us on Facebook

RELIANT · FIRE · APPARATUS
F R A



DSC06230



DSC06231



DSC06232



DSC06233



DSC06234



DSC06235



DSC06236



DSC06237



DSC06238



DSC06239



DSC06240

https://reliantfire.com/

Find us on Facebook

An Oshkosh Corporation Company